





Thank you for choosing our products.
Important - please assemble and use it following the
instructions. We recommend two people to assemble
the product easier and faster.


NO.	QTY.	LINEDRAWING
(A)	18	
(B)	18	
(C)	24	
(D)	6	 7x40
(E)	4	 3.5x35
(F)	71	 3.5x14
(G)	16	 3x14
(H)	1	
(I)	5	
(J)	6	
(K)	2	
(L)	4	 3x14
(M)	2	 3.5x35 3.5x14
(N)	4	
(O)	8	
(P)	1	
(Q)	1	

PARTS LIST




NO.	QTY.
①	1
②	1
③	1
④	1
⑤	1
⑥	1
⑦	1
⑧	2
⑨	1
⑩	1
⑪	1
⑫	1
⑬	1
⑭	1
⑮	1
⑯	1
⑰	4

1




F	
4x	
H	
1x	

2




I	
5x	
F	
25x	

3





A	
2x	
B	
2x	

4





A	
2x	
B	
2x	



5





6







7





8









13





14




15



16



17



6x




24x



3x

18



C



18x



2x

N




1x

O



2x

19



M

M