



Attached: coating table installation manual



Note: This product contains one upper surface, one lower surface, four supports, a package of screws (4 long screws, 4 regular screws), one square basin, one round basin, one square basin, one alliance, and one blue shelf (BOOA 1000C (no storage porridge) Installation instructions (This product is a stainless steel product. Please wear rubber gloves when installing to avoid milk injury)



① Divide the four legs into eight pieces and insert them into the four holes in the upper plate, and use the Naisi to fix the inclination



② Place the lower plate in the position shown above and secure it with long screws (Hongxing gongpian is used here)



③ Place the square basin and the round basin in the position shown above



④ Place it on the blue shelf to complete the installation. The picture above is a schematic diagram of the completed powder table installation