





EN_IMPORTANT, RETAIN FOR FUTURE REFERENCE: READ CAREFULLY.

FR_IMPORTANT: A LIRE ATTENTIVEMENT ET À CONSERVER POUR CONSULTATION ULTÉRIEURE.


ES_IMPORTANTE, LEA Y GUARDE PARA FUTURAS REFERENCIAS.

DE_WICHTIG! SORGFÄLTIG LESEN UND FÜR SPÄTER NACHSCHLAGEN AUFBEWAHREN.


IT_IMPORTANTE! CONSERVARE IL PRESENTE MANUALE PER FUTURO RIFERIMENTO E LEGGERLO ATTENTAMENTE.




① x1




② x2




③ x2




④ x1




⑤ x2




⑥ x2




⑦ x1







⑧ x2



⑨ x2




HARDWARE

A x12
 M6*30
 +1(spare)

B x12
 M6*40
 +1(spare)

C x12
 +1(spare)

Y x 1
 M5





Bx4

Y




Bx4

Y




Bx4


Y




Y



Y




Y






Ax4

Y




Ax4



Y



Ax4

Y



**Cx4****Cx4****Cx4**