





OPERATING INSTRUCTIONS



8 x (H1)



12 x (H2)




16x(H3)




16x(H4)




46x(H5)




3x(H6)



3x(H7)



3x(H8)



3x(H9)



4 x (H10)



4 x (H11)





2x(H12)



2x(H13)




4x (H14)




x2


Step 1




Step 2




Step 3



Step 4







Step 5




Step 6

X2




Step 7


X2




Step 8



Step 9



Step 10



Step 11

