

LEG ASSEMBLY INSTRUCTION SHEET

ALLOW 10 MINUTES FOR ASSEMBLY

1. Make sure you have the following parts:

(4) Legs

(4) 2.5" Bolts

(4) Washers

A PHILLIPS HEAD SCREWDRIVER IS NEEDED FOR ASSEMBLY

1. Working on a clean surface, turn the unit on its back with the unit base facing your work area.

2. Locate T-nut hole in frame and insert 2.5" bolt and washer through leg into hole.

1. Attach legs placing (4) – 2.5" bolts & washers (1 of each per leg) in t-nuts located on bottom of unit

2. Repeat the above procedures for the remaining legs

3. Turn the unit upright and place in the desired location