


# Office Furniture Distributors

X-5M  
PARTS  
① X 1



A.M6\*25 X 4



② X 1



B.M6\*20 X 4

③ X 1



C.M6\*40X4



④ X 1




D.X4

⑤ X 1



E.X 1

⑥ X 1



F.X5



⑦ X 1



G.X2




H.X 2




**NOTICE:**  
EVERY 6 MONTHS,PLEASE MAKE SURE ALLBOLTS,  
SCREWS AND KNOBS ARE FULLY TIGHTENED TO  
ENSURE STABILITY.

## Assembly Instructions


STEP 1




STEP 2




STEP 3



STEP 4



STEP 5



Call17 Foam  
P2 Seat Board Compliant  
Made in China