

































ASSEMBLING INSTRUCTION





|   |                                                                                                   |     |   |                                                                                                  |     |
|---|---------------------------------------------------------------------------------------------------|-----|---|--------------------------------------------------------------------------------------------------|-----|
| A |                  | X62 | N |               | X8  |
| B | <br>ø15*12mm     | X38 | P |               | X1  |
| C | <br>ø15*10mm     | X24 | R |               | X1  |
| D | <br>CL DL DR CR | X6  | S | <br>M3.5*14mm | X2  |
| E | <br>ø6*30mm    | X30 | T | <br>M3*14mm | X16 |
| F | <br>M3*12mm    | X60 | U |             | X8  |
| G | <br>M4*35mm    | X24 | V |             | X62 |
| H | <br>M4*18mm    | X12 | W |             | X2  |
| J |                | X6  | X |             | X4  |
| L |                | X1  | Y |             | X5  |
| M |                | X2  |   |                                                                                                  |     |

|   |                                                                                     |    |   |                                                                                       |    |
|---|-------------------------------------------------------------------------------------|----|---|---------------------------------------------------------------------------------------|----|
| ① |    | X1 | ⑩ |    | X1 |
| ② |    | X1 | ⑪ |    | X1 |
| ③ |    | X1 | ⑫ |    | X1 |
| ④ |  | X2 | ⑬ |  | X6 |
| ⑤ |  | X1 | ⑭ |  | X6 |
| ⑥ |  | X1 | ⑮ |  | X6 |
| ⑦ |  | X2 | ⑯ |  | X6 |
| ⑧ |  | X4 | ⑰ |  | X6 |
| ⑨ |  | X1 | ⑲ |  | X1 |


Step:1





|   |                                                                                     |    |
|---|-------------------------------------------------------------------------------------|----|
| A |  | X3 |
|---|-------------------------------------------------------------------------------------|----|



Step:2





|   |                                                                                                   |    |
|---|---------------------------------------------------------------------------------------------------|----|
| B | <br>ø15*12mm | X3 |
| E | <br>ø6*30mm  | X2 |
| V |              | X3 |



Make sure board 1 and board 2 are even when installing them.

Step:3


|   |                                                                                             |    |
|---|---------------------------------------------------------------------------------------------|----|
| T |  M3*14mm | X4 |
| X |          | X4 |




Step:4



|   |                                                                                       |    |
|---|---------------------------------------------------------------------------------------|----|
| L |  | X1 |
|---|---------------------------------------------------------------------------------------|----|

Buckle the light strip in.






Step:5

|   |                                                                                             |    |
|---|---------------------------------------------------------------------------------------------|----|
| T |  M3*14mm | X4 |
| M |          | X2 |




Step:6


|   |                                                                                       |    |
|---|---------------------------------------------------------------------------------------|----|
| A |  | X4 |
|---|---------------------------------------------------------------------------------------|----|







Step:7





|   |                                                                                                 |    |
|---|-------------------------------------------------------------------------------------------------|----|
| B | <br>φ15*12mm | X4 |
| E | <br>φ6*30mm  | X4 |
| V |              | X4 |




Step:8




|   |                                                                                       |    |
|---|---------------------------------------------------------------------------------------|----|
| A |  | X6 |
|---|---------------------------------------------------------------------------------------|----|





Step:9

|   |                                                                                                |    |
|---|------------------------------------------------------------------------------------------------|----|
| E | <br>ø6*30mm | X4 |
|---|------------------------------------------------------------------------------------------------|----|




Step:10


|   |                                                                                       |    |
|---|---------------------------------------------------------------------------------------|----|
| N |  | X4 |
| R |  | X1 |








Step:11

|   |                                                                                                |     |
|---|------------------------------------------------------------------------------------------------|-----|
| F | <br>M3*12mm | X12 |
| D | <br>CR CL   | X3  |





Punch the position  
of the hole 1




Punch the position  
of the hole 1


# Step:12




|   |                                                                                                 |    |
|---|-------------------------------------------------------------------------------------------------|----|
| B | <br>φ15*12mm | X6 |
| E | <br>φ6*30mm  | X2 |
| V |              | X6 |




# Step:13








Step:14

|   |                                                                                                |    |
|---|------------------------------------------------------------------------------------------------|----|
| E | <br>ø6*30mm | X2 |
| N |             | X2 |
| R |             | X1 |





Step:15


|   |                                                                                       |    |
|---|---------------------------------------------------------------------------------------|----|
| A |  | X3 |
| Y |  | X1 |




Step:16





|   |                                                                                                 |    |
|---|-------------------------------------------------------------------------------------------------|----|
| B | <br>φ15*12mm | X3 |
| E | <br>φ6*30mm  | X2 |
| V |              | X3 |





Step:17




|   |                                                                                       |    |
|---|---------------------------------------------------------------------------------------|----|
| A |  | X4 |
|---|---------------------------------------------------------------------------------------|----|





Step:18




|   |                                                                                                 |    |
|---|-------------------------------------------------------------------------------------------------|----|
| B | <br>ø15*12mm | X4 |
| E | <br>ø6*30mm  | X2 |
| V |              | X4 |

Step:19


|   |                                                                                       |    |
|---|---------------------------------------------------------------------------------------|----|
| N |  | X2 |
| R |  | X1 |




Step:20

|   |                                                                                                |     |
|---|------------------------------------------------------------------------------------------------|-----|
| F | <br>M3*12mm | X12 |
| D | <br>CR CL   | X3  |

Punch the position  
of the hole 1




Punch the position  
of the hole 1



CR CL



Punch the position  
of the hole 1








Punch the position  
of the hole 1




Step:21


|   |                                                                                     |     |
|---|-------------------------------------------------------------------------------------|-----|
| A |  | X18 |
| Y |  | X4  |




Step:22



|   |                                                                                                 |    |
|---|-------------------------------------------------------------------------------------------------|----|
| B | <br>Ø15*12mm | X9 |
| E | <br>Ø6*30mm  | X6 |
| V |              | X9 |




Step:23








Step:24



|   |                                                                                                 |    |
|---|-------------------------------------------------------------------------------------------------|----|
| B | <br>ø15*12mm | X9 |
| E | <br>ø6*30mm  | X6 |
| V |              | X9 |





Step:25




|   |                                                                                                  |    |
|---|--------------------------------------------------------------------------------------------------|----|
| T | <br>M3*14mm | X8 |
| U |             | X8 |


Step:26

|   |                                                                                                  |    |
|---|--------------------------------------------------------------------------------------------------|----|
| P |               | X1 |
| S | <br>M3.5*14mm | X2 |






Step:27

|   |                                                                                                  |     |
|---|--------------------------------------------------------------------------------------------------|-----|
| G | <br>M4*35mm | X24 |
|---|--------------------------------------------------------------------------------------------------|-----|



Step:28


|   |                                                                                     |     |
|---|-------------------------------------------------------------------------------------|-----|
| A |  | X24 |
|---|-------------------------------------------------------------------------------------|-----|



X 6

Step:29


|   |                                                                                                   |     |
|---|---------------------------------------------------------------------------------------------------|-----|
| C | <br>ø15*10mm | X24 |
| V |              | X24 |



X 6

Step:30


|   |                                                                                     |     |
|---|-------------------------------------------------------------------------------------|-----|
| J |  | X6  |
| H |  | X12 |



X 6


Step:31

|   |                                                                                                  |     |
|---|--------------------------------------------------------------------------------------------------|-----|
| D |             | X6  |
| F | <br>M3*12mm | X36 |




X 6

Step:32



Step:33



Step:34

