


Assembly Instructions



ATTENTION:

We will provide our best customer support.

If you have any questions or issues during installation.


Please send an email with your

telephone number and address. We will provide installation support, guided videos and offer replace parts for any defective parts.


All queries will be addressed within 24 hours.

Customer satisfaction is crucial for us.


PARTS LIST



HARDWARE LIST



HARDWARE LIST



ASSEMBLY

STEP1





S2 X 4

P1 X 2

P2 X 2

1 X 1



1. Assemble P1 on Part 1 with S2 screws.

2. Assemble P2 on Part 1 with S2 screws.



STEP2



S2 X 8


P7 X 4

2 X 1



1. Assemble Part 2 & P7 with S2 screws.

STEP3





S2 X 2

S3 X 2

P1 X 1

P2 X 1



1. Tighten Part 2 with S2 screws. (* Note the assemble direction of S2 screws.)

2. Tighten P1 on Part 2 with S3.

3. Tighten P2 on Part 2 with S3.

STEP4



S2 X 1


S3 X 3

P3 X 1

3 X 1

7 X 1

8 X 1




1. Hang the four hooks of Part 7 with the rope at the bottom of Part 2.

2. Assemble Part 3 on P1 & P2 with S3 screws.

3. Assemble P3 on Part 2 with S2 screw, then assemble Part 8 on P3 with S3 screw.

STEP5



S1 X 4


S4 X 2

P3 X 1

P4 X 1

P5 X 1

6 X 1




1. Connect Part 2 and Part 6 together with S1 screws and S4 hinges.

2. Assemble P3 & P4 on Part 3.

3. Assemble P5 on Part 8.


STEP6



S2 X 8

P7 X 4

4 X 1



1. Assemble Part 4 & P7 with S2 screws.

STEP7


T



S2 X 3

S3 X 1

P6 X 2




1. Assemble Part 4 on P3 & P4 with S2 screws.

2. Tighten one of P6 on Part 4 with S3 screw.

3. Assemble another P6 on the top with S2 screw.


STEP8

5 X 2



1. Connect Part 5 and P6 as shown in the picture.

STEP9



To enhance the stability of the cat tree, expansion screws can be screwed into the wall.