









JA25012


ASSEMBLY INSTRUCTIONS







+Spare X 1 A x 3  M8*100mm	+Spare X 1 B x 9  M8*55mm	+Spare X 2 C x 16  Ø7.8*30mm	D x 1  M8*110mm	E x 4  M8*70mm	F x 2  60*20*2mm
+Spare X 1 G x 5  M6*15mm	+Spare X 1 H x 9  M8	+Spare X 1 I x 9  Ø16mm	J x 8 	+Spare X 1 K x 5  Ø9.8*30mm	L x 2 
M x 1  5mm	N x 1  4mm	+Spare X 1 O x 9  Ø50mm			


1




C	x2	D	x1	H	x2	I	x2	J	x2	L	x2
											
Ø7.8*30mm		M8*110mm		M8		Ø16mm					

2



M	x1	A	x1	C	x2	H	x1	I	x1	J	x1	L	x1
													
5mm		M8*100mm		Ø7.8*30mm		M8		Ø16mm					

3



M	x1
5mm	

L	x1

J	x1


I	x1
Ø16mm	

H	x1
M6	

C	x2
Ø7.8*30mm	


A	x1
M8*100mm	

4



K	x4
Ø7.8*30mm	

5



G	x4
M6*15mm	

M	x1
5mm	

N	x1
4mm	


B	x4
M6*55mm	

C	x4
Ø7.8*30mm	

E	x4
M6*70mm	

F	x2
60*20*2mm	

6




L	x1

H	x4
M8	

I	x4
Ø16mm	

J	x4

7



8

