



Diagram illustrating assembly instructions and safety warnings:

- Top Section:** Shows a warning triangle (exclamation mark) next to a box containing icons for an Allen key, a wrench, and a power drill with a slash through it, indicating that a power drill should not be used. To the right is a clock icon with the text "20'", indicating a 20-minute assembly time.
- Bottom Section:** Shows a warning triangle (exclamation mark) next to a box containing icons for a block of material being placed on a surface and a block being lifted, indicating a lifting or placement instruction. To the right is a person icon with the text "2", indicating that two people are required for assembly.




A




x 16

B




x 26

C




x 6

D




x 48

E




x 6

F




x 6

G




x 1

H




x 1

I




x 4

J




x 1

K




x 2

L




x 2

M






x 2

N






x 2





1










2



3



4






5

B  
M8  
x  
45  
x 18

D  
x 18

G  
x 1

J  
x 1



6



D  
x 6

E  
x 6


F  
x 6


H  
x 1


K  
x 2





7

**B**  
  
M8  
x  
45  
x 4

**D**  
  
x 4

**G**  
  
x 1



!

