












Assembly Instruction




NO.	QTY.	LINEDRAWING
(A)	40	7x50 
(B)	4	
(C)	2	
(D)	36	
(E)	8	
(F)	40	∅15 
(G)	1	

 
Hammer and Screwdriver
are not included !!





PARTS LIST





NO.	QTY.
①	1
②	1
③	1
④	1
⑤	3
⑥	2
⑦	1
⑧	1
⑨	1
⑩	1
⑪	1
⑫	1
⑬	2



1





2





3





4





5



6



7



8

