
















			
A(X2)		D(X1)	
			
B(X2)		J(X1)	
			
H(X4)	F(X4)	(X1)1286X15X30	
			
T(X9)	E(X1)	(X2)1200X15X30	
			
	H(X2)	G(X1)	
			
	M4x13mm (X35)		

1




A(X1)

(X1)1200X15X30




T(X2)


M4x13mm
(X4)



2




D(X1)




CLICK

3




A(X1)




(X1)1200X15X30




T(X3)




M4x13mm
(X6)




4




5




B(X2)




H(X4)




6




7




8




F(X4)




9




I(X1)




M4x13mm
(X1)




10




J(X1)




(X1)1286X15X30




T(X4)




M4x13mm
(X8)




11




G(X1)




E(X1)




M4x13mm
(X2)




12




H(X2)




M4x13mm
(X4)



13



M4x13mm
(X10)



14

