






ASSEMBLE INSTRUCTION

Ax1  A1 1PC	 A2 5PCS	Ix2 
Bx1 	Jx1 	
Cx5  C1  C2	Kx8 +1(spare)  M6x20mm	
Dx1 	Lx4 +1(spare)  M6x25mm	
Ex1 	Mx10 +1(spare)  M6x12mm	
Fx1 	Nx10 +1(spare)  M6x30mm	
Gx1 	Ox1  M6	
Hx2 	Px6 	

