


Attention: Please don't tighten the screws completely and go back later for a final tightening of all the screws after pieces are aligned with each other. If the screws are tightened initially, subsequent hole positions may be misaligned.



Hardware arts



M6X35
① 6PCS



M6X45
② 8PCS



M6X55
③ 2PCS



M8X15
④ 8PCS




M8X45
⑤ 12PCS




4#
⑥ 2PCS


Part list




① 2PCS




② 1PC




③ 2PCS




④ 2PCS




⑤ 2PCS



⑥ 2PCS



⑦ 1PC




⑧ 10PCS



⑨ 2PCS






⑩ 4PCS





⑪ 2PCS


Step:1

	M6X45	B	4PCS		4#	F	1PC
---	-------	---	------	--	----	---	-----






Step:3

	M8X45	E	8PCS		4#	F	1PC
---	-------	---	------	---	----	---	-----






Step:2

	M6X45	B	4PCS		4#	F	1PC
---	-------	---	------	---	----	---	-----









Step:4

	M6X35	A	6PCS
	4#	F	1PC




Step:5

	M8X45	E	4PCS
	M8X15	D	8PCS
	M6X55	C	2PCS
	4#	F	1PC



Step:6



Step:7

