ASSEMBLY INSTRUCTIONS DINING TABLE Parts Check List Qty Components Code TABLE TOP xO1 (A)METAL LEG x02 X STRETCHER xO1 Hardware Check List Description Qty Code Pan head allen bolt M8x20 (8) x12 - PLEASE DO NOT DISCARD ANY OF THE PACKAGING UNTIL YOU HAVE CHECKED ALL THE PARTS AND THE PACKS OF HARDWARE. 02 Jcbc M6x20 xO4 - BEFORE YOU BEGIN TO ASSEMBLE YOUR NEW PIECE OF FURNITURE, PLEASE CHECK TO ENSURE THAT ALL PARTS HAVE O3 Spring washer M6 xO4 BEEN SUPPLIED. - FOLLOW INSTRUCTIONS CLOSELY AS DEVIATION FROM THEM MAY 04 Flat washer M6 xO4 VOID YOUR WARRANTY AND PRESENT A POSSIBLE SAFETY RISK. - IT IS RECOMMENDED THAT ASSEMBLY IS DONE ON A SOFT 05 Allen key M4 xO1 SURFACE LIKE CARPET TO AVOID ANY DAMAGE. - PERIODICALLY CHECK AND RE-TIGHTEN ANY FASTENERS. WIPE 06 Allen key M5 xO1 DOWN ALL SURFACES WEEKLY WITH A CLEAN CLOTH. DO NOT CLEAN ANY SURFACES WITH HARSH ABRASIVES OR CHEMICALS. 05 06 **ADJUST FEET LEVELERS**