



Additional Tools Required



Surface installation

Mark four (4) mounting holes on the wall corresponding to the pre-drilled hole lo cations in the mounting bars on theinside back panel of the cabinet.



