


ASSEMBLY INSTRUCTION

SS19055




Before initial use, please charge the product first (part L) .
Fast charging takes 4 hours to complete. After being fully charged,
The light will remain on for more than 4 hours.


Parts & Tools

PART	QTY	PICTURE	PART	QTY	PICTURE
A	1		H	1	
B	1		I	1	
C	1		J	1	
D	4	 (M8X16)	K	1	
E	4	 (Ø8)	L	1	
F	2		M	1	
G	4		N	2	
			P	4	


step 1




step 4



step 7




step 10




Clockwise to open, counterclockwise to close.


step 2




step 5




step 8




step 11




step 3



step 6



step 9



step 12

