



WRC51001 ASSEMBLY INSTRUCTION


P1 Top (x 1)




P2 Leg (x 4)



P3 Brass (x 4)



H1 Steel allen wrench (x 1)



H2 Steel allen bolt (Short) , washer
& lock (x 16)



H3 Steel allen bolt (Long) , washer
& lock (x 16)

