



Assembly instruction



ϕ 8*60mm


H 3 PCS



ϕ 6*38mm




ϕ 15*11mm




ϕ 8*40mm



ST3. 5*30mm





A	20 PCS	B	20 PCS	C	16 PCS	D	40 PCS	E	50 PCS	F	60 PCS	J	3 PCS
---	--------	---	--------	---	--------	---	--------	---	--------	---	--------	---	-------



1


Step1*4



		$\phi 8*40\text{mm}$ ST3. 5*30mm	
C	8 PCS	D	12 PCS


2

Step2*2



		$\phi 8*40\text{mm}$ ST3. 5*30mm	
C	4 PCS	D	20 PCS

3




φ 6*38mm

A 8 PCS



φ 15*11mm

B 8 PCS



φ 8*40mm



C 4 PCS



ST3. 5*30mm

D 3 PCS

4




φ 6*38mm

A 4 PCS



φ 15*11mm

B 4 PCS



φ 8*40mm


C 4 PCS



ST3. 5*30mm

D 3 PCS

5



Φ 6*38mm

A 4 PCS





Φ 15*11mm

B 4 PCS

Step6*4

6



Φ 8*40mm

C 8 PCS





ST3. 5*30mm

D 12 PCS

Step7*2

7



φ 8*40mm


C 8 PCS



ST3. 5*30mm

D 12 PCS

8




φ 6*38mm

A 4 PCS



φ 15*11mm

B 4 PCS




φ 8*40mm

C 3 PCS




ST3. 5*30mm

D 3 PCS



φ 8*60mm

H 1 PCS




$\phi 6*38\text{mm}$

A 4 PCS



$\phi 15*11\text{mm}$

B 4 PCS




$\phi 8*40\text{mm}$

C 3 PCS




ST3. 5*30mm

D 3 PCS



 ϕ 6*38mm	 ϕ 15*11mm	 ϕ 8*40mm
A 26 PCS	B 14 PCS	C 7 PCS




Φ 15*11mm

B 12 PCS


12

Part E for big hole,
Part F for small hole





E	50 PCS
F	60 PCS

13



J	3 PCS



J	3 PCS
---	-------