

# This manual shall prevail

|             |             |             |             |             |             |             |             |              |             |             |
|-------------|-------------|-------------|-------------|-------------|-------------|-------------|-------------|--------------|-------------|-------------|
| <b>A X1</b> | <b>B X1</b> | <b>C X1</b> | <b>D X1</b> | <b>E X1</b> | <b>F X1</b> | <b>G X1</b> | <b>H X4</b> | <b>I X12</b> | <b>J X4</b> | <b>K X1</b> |
|             |             |             |             |             |             |             |             |              |             |             |
|             |             |             |             |             |             |             | M6*16       | M6*30        | M6*25       |             |

**1**

**2**

Put the screws in the holes,tight the screws, but not too tight,70% is ok.

**3**

**4**

**5**

Put the screws in the holes,tight the screws, but not too tight,70% is ok.

**6**

Tight all the screws to 100%  
If needed, use adjustable foot pads to level chair.