


PART LIST






ACCESSORIES



HARDWARE




PRE-INSTALLED PARTS

P1 FOR FIG. 1	P2 FOR FIG. 1	P3 FOR FIG. 1
ΙX	x4	x16
Motor	Apron Corner	T - Nut

ASSEMBLY

FIG. 1












FIG. 2





