






Diagram illustrating assembly steps and safety warnings:






- Step 1:** Shows an L-shaped metal bracket and a power drill with a slash through it, indicating that a drill should not be used. A warning triangle with an exclamation mark is positioned to the right.
- Step 2:** Shows a rectangular block being placed on a surface and another block being inserted into a slot. A warning triangle with an exclamation mark is positioned to the right.

Estimated time: **20'**

Number of people required: **2**



1

|   |   |  |  |   |
|---|---|--|--|---|
| <p>1</p>  <p>x 1</p> | <p>2</p>  <p>x 4</p> | <p>A</p>  <p>M8<br/>x<br/>20<br/>x 16</p> | <p>B</p>  <p>x 16</p> | <p>C</p>  <p>x 1</p> |
|---|---|--|--|---|

