











ASSEMBLY INSTRUCTION




Notes: Don't fully tighten screws until all parts are confirmed in place to avoid misalignment.






A	X16	B	X16	C	X24	D	X6	E	X32
									
Ø6X35mm		Ø15X12mm		Ø8X30mm		Ø10X50mm		Ø7X47mm	

F	X1	G	X8	H	X8	I	X8	J	X12
									
M4X64mm		M6X12mm		M6X15mm		M6X30mm		M6X45mm	



K	X4	L	X8	M	X12	N	X12
							
40X20mm		M6XØ30mm		3.5X14mm		14X14X9mm	

STEP 1




A	X16
Ø6X35mm	

STEP 2




B	X8	C	X4
Ø15X12mm		Ø8X30mm	


STEP 3



X2

B	X8	C	X4
			
Ø15X12mm		Ø8X30mm	


STEP 4



X2


C	X8	E	X16	F	X1
					
Ø8X30mm		Ø7X47mm		M4X64mm	

STEP 5




L	X8
	
M6XØ30mm	

STEP 6



X2


STEP 7



X2

C	X8	E	X16
			
Ø8X30mm		Ø7X47mm	


STEP 8



X2


M	X12	N	X12
			
3.5X14mm		14X14X9mm	

STEP 9





D	X6
	
Ø10X50mm	


STEP 10




H	X8	K	X4
			
M6X15mm		40X20mm	

STEP 11





J	X12
	
M6X45mm	

STEP 12




I	X8
	
M6X30mm	

STEP 13



G	X4
A small icon of a screw with a Phillips head.	
M6X12mm	

STEP 14



G	X4
A small icon of a screw with a Phillips head.	
M6X12mm	

STEP 15

