

















ASSEMBLY INSTRUCTION




ASSEMBLY INSTRUCTION

① 1PC 	② 3PCS 	③ 1PC 
④ 1PC 	⑤ 1PC 	⑥ 1PC 
⑦ 1PC 	⑧ 1PC 	⑨ 1PC 
⑩ 1PC 	⑪ 1PC 	⑫ 2PCS 
⑬ 1PC 	⑭ 1PC 	

ASSEMBLY INSTRUCTION

A 36PCS  M6*40	B 36PCS  Φ 15*10.5	C 4PCS  Φ 6*30	D 6PCS  M6*40	E 12PCS  M6*30
F 4PCS  M6*25	G 1PC  Ø50	H 4PCS  M8	I 22PCS 	J 14PCS 
				


step 1



ASSEMBLY INSTRUCTION


step 2

C 2PCS

 $\phi 6*30$ 


step 3

B 8PCS

 $\phi 15*10.5$ 

step 4

B 6PCS


 $\phi 15*10.5$ 

step 5


D 6PCS



M6*40



step 6



E 12PCS


M6*30

H 4PCS

M8

step 7


Please note that! The 10th panel has a dimension direction.



B 6PCS

 $\phi 15*10.5$

step 8



B 10PCS

 $\phi 15*10.5$

C 2PCS


 $\phi 6*30$

ASSEMBLY INSTRUCTION

step 9

B 6PCS


 $\phi 15 \times 10.5$



step 10

F 4PCS


 $M6 \times 25$




step 11

G 1PC

 $\phi 50$



step 12



OK