
Parts/Hardware list

A	Top Frame	1 PC	Е	Short Leg Tube	4PCS
В	Thread Rod	4PCS	F	Bottom Foot	4 PCS
С	Long Leg Tube	4PCS	G	Felt Pad	4PCS
D	Stretcher	1 PC	Н	Glass Top	1PC

- 1. Take the parts carefully out of the carton, and place them on a flat and soft surface, making sure that the parts will not be damaged.
- 2. Place Top Frame (A) upside down on a flat & soft surface.
- 3. Scew 4 Thread Rod (B) on Top Frame (A) individually.
- 4. Put the Long Leg Tube (C) on the Thread Rod(B), let Thread rods (B) pass through 4 Long Leg Tube (C).
- 5. Put the Stretcher(D) on the Thread Rod(B), Let the Thread Rod(B) pass through the 4 holes of the Stretcher(D).
- 6. Put the Short Leg Tube (E) on the Thread Rod(B), let the Thread Rod(B) pass through the Short Leg Tube (E).



- 7. Screw 4 Bottom Foot (F) on the end of the Thread Rod(B) till all parts are tight.
- 8. Stick the Felt pads (G) on the bottom of 4 Bottom Feet (F).
- 9. Turn over table, and place the Class Top (H) on the Top Frame (A) as show in above picture (2).
- 10. To Clean, wipe with dry cloth.