

Attention: Do not tighten the screws until all of them are in right positions.

Ax4	Bx4	Cx2	Dx8	Ex16	Fx1
			 M6x30	 M6x12	
1			2		
3			4		
ⓓ x4			ⓔ x8		