
Assembly Instruction

Console Table



ASSEMBLY TIPS:

1. Remove hardware from box and sort by size.

2. Please check to see that all hardware and parts are present prior to start of assembly.

3. Please follow attached instructions in the same sequence as numbered to assure fast & easy assembly.

Parts List

Number	Name	Part	Qty
1	Desktop		x1PC
2	Right Leg		x1PC
3	Left Leg		x1PC
4	Corner		x2PCS
5	Sheft		x1PC

Number	Hardware	Part	Qty
A	8x25	0	x16+1PCS
В	8x35		x4+1PCS
С	Flat Washer	\bigcirc	x20+4PCS
D	Allen Wrench		x1PC
E	Plastic Cap		x16+1PCS
F	3x14	E DO	x12+1PCS
G			x1PC
н			x2PCS

