


Large Cat Cage

GH301




USER MANUAL

COMPONENTS


Parts List (Box A)

⑤




1PC

⑥




1PC

②①




6PCS

②③




10PCS

②⑨










2PCS

③①











2PCS

COMPONENTS








<p>31</p>  <p>2PCS</p>	<p>33</p>  <p>1PC</p>
<p>34</p>  <p>1PC</p>	<p>39</p>  <p>1PC</p>
<p>40</p>  <p>1PC</p>	<p>41</p>  <p>1PC</p>
<p>42</p>  <p>1PC</p>	

COMPONENTS

Parts List (Box B)









<p>①</p>  <p>1PC</p>	<p>②</p>  <p>1PC</p>
<p>③</p>  <p>1PC</p>	<p>④</p>  <p>1PC</p>
<p>⑦</p>  <p>1PC</p>	<p>⑧</p>  <p>1PC</p>
<p>⑨</p>  <p>1PC</p>	<p>⑩</p>  <p>1PC</p>

COMPONENTS








<p>22</p>  <p>3 PCS</p>	<p>24</p>  <p>2 PCS</p>
<p>32</p>  <p>1 PC</p>	<p>35</p>  <p>1 PC</p>
<p>36</p>  <p>1 PC</p>	<p>37</p>  <p>1 PC</p>
<p>38</p>  <p>1 PC</p>	

COMPONENTS









Parts List (Box C)

<p>⑪</p>  <p>1PC</p>	<p>⑫</p>  <p>1PC</p>
<p>⑬</p>  <p>1PC</p>	<p>⑭</p>  <p>1PC</p>
<p>⑮</p>  <p>1PC</p>	<p>⑯</p>  <p>1PC</p>
<p>⑰</p>  <p>1PC</p>	<p>⑱</p>  <p>1PC</p>

COMPONENTS


<p>19</p>  <p>1 PC</p>	<p>20</p>  <p>1 PC</p>
<p>24</p>  <p>4 PCS</p>	<p>25</p>  <p>1 PC</p>
<p>26</p>  <p>4 PCS</p>	<p>27</p>  <p>2 PCS</p>
<p>28</p>  <p>2 PCS</p>	

COMPONENTS


<p>A</p>  <p>M5. 0x45mm +1(spare) 28PCS</p>	<p>B</p>  <p>M5. 0x65mm +1(spare) 50PCS</p>
<p>C</p>  <p>M3. 5x35mm +2(spare) 92PCS</p>	<p>D</p>  <p>M3. 5x20mm +2(spare) 40PCS</p>
<p>E</p>  <p>M3. 0x10mm +2(spare) 24PCS</p>	<p>F</p>  <p>4PCS</p>
<p>G</p>  <p>M5.0x55mm +1(spare) 16PCS</p>	<p>H</p>  <p>M3. 5x25mm +1(spare) 12PCS</p>

Assembly Steps


1




E x 8pcs



F x 2pcs



2




A x 8pcs

Assembly Steps

3




A x 16pcs





4



A x 4pcs



5





B x 4pcs



G x 8pcs

6





B x 4pcs





G x 8pcs





7







8




9



10




11




B x 3pcs

12




B x 3pcs

13




D x 20pcs

14




D x 8pcs


15



16




17




D x 12pcs

18




B x 6pcs

19



B x 6pcs


20




C x 24pcs


Please align the wood parts at the edge before you drive the screws.

21



22





CONGRATULATIONS
YOU ARE DONE!