







ASSEMBLY INTRODUCTION






Exploded View





Fitting

 A x 53 M6 x 35 mm	 B x 53 φ15 x 9.5 mm	 C x 34 φ6 x 30 mm	 D x 6 φ4 x 40 mm	 E x 8 φ3 x 12 mm
 F x 8	 G x 2 φ4 x 12 mm	 H x 2	 I x 2 φ4 x 40 mm	 J x 24 φ3 x 14 mm
 CL x 1 250 mm	 DL x 1 250 mm	 DR x 1 250 mm	 CR x 1 250 mm	


Step 1




Step 2






Step 3





Step 4






Step 5






Step 6






Step 7





Step 8





Step 9





Step 10





Step 11





Step 12






Step 13






Step 14





Step 15




Step 16




Step 17




Step 18





Step 19





Step 20





Step 21




Step 22



Step 23



Step 24



Step 25

