










Assembly Instructions






We recommend using hand tools for assembly.

If an electric screwdriver is used, reduce power and torque to avoid damage to the product.



(Install tip-over restraint provided)







Use of tip-over restraints may only reduce but not eliminate, the risk of tip-over.



⚠ Caution

Make sure all parts are included. Most board parts are labeled or stamped on the raw edge. Contact us for a free replacement if you encounter any damaged or missing parts.

Parts List


 ① 5 pcs	 ② 1 pc	 ③ 1 pc	 ④ 2 pcs	 ⑤ 1 pc
 ⑥ 2 pcs	 ⑦ 5 pcs			

Hardware List


 W-1 36 pcs	 W-2 36 pcs	 W-3 6 pcs	 W-4 32pcs	 W-5 1 pc	 W-6 1 pc	 W-7 36 pcs
--	--	---	---	---	--	--

Installation of Cams and Pins


Screw the pin into the hole. To set the cams correctly, ensure that the arrow on the cam is opening to the hole of the pin it is locking. Lock the cam by turning the cam head with a screwdriver until it is tightened. Please do not use an electric screwdriver to assemble the unit.



Read each step carefully before starting. It is very important that each step of instruction is performed in the correct order. If these steps are not followed in sequence, assembly difficulties will occur.




1



持
M6X40MM

W-1 12 pcs
W-2 12 pcs


2




持
M6X40MM

W-1 4 pcs
W-2 4 pcs

3




4



⚠ Caution

5

Please keep the upper and lower cabinets aligned when they are placed to facilitate the installation of back panel #7




W-4
32 pcs

⚠ Caution

When handling, please carry the middle of the handling, to prevent the middle cork W-3 fracture.

6



W-7
36 pcs

Assembly Instructions



Plastic anchor
M4*30:1pc



Nylon Strap
8*250:1pc



Plastic connectors
2pcs




M4*40
1pc


M4*16
1pc _)




Step 1




Step 2




Step 3




Step 4



Step 5



Step 6



Thank you for your support!

