

















A1	8 x 35 mm	x28	C3	6,3 x 16 mm	x16	E0		x16
E1	15 x 12 mm	x16	F1	6 x 34 mm	x16	I18		x12
M		x1	O2		x6	X4		x4







1	2005	120	28	x2	2/3
2	2005	90	28	x2	3/3
3	960	800	28	x1	1/3
4	960	400	28	x1	1/3
5	846	200	16	x2	1/3





1 ►




2 ►





5▶



6▶

