













Hardware



A x46(+2)	B x46(+2)	C x44(+2)	D x11	E x16(+1)	F x8
					
Ø6x35mm	Ø15x10mm	Ø6x30mm	Ø4x35mm	Ø3x12mm	Ø20mm
G x4	H x4	I x2	J x4	K x16	L x16
					
			Ø4x12mm		Ø3x16mm
M x20	N x2	O x8	P x4	Q x6	R x12
	 N-1  N-2				
Ø5x40mm					
S x2	T x2	U x52(+2)	V x1	W x2	X x1
				 W-1  W-2	
		Ø3x14mm			M4mm
Y x1	CL x1	CR x1	DL x1	DR x1	
					
	L300mm	L300mm	L300mm	L300mm	

1




x2


A x6	Y x1	O x4	U x12
			
Ø6x35mm			Ø3x14mm



4



Front.

Distance: $a \gg b$ 



Note: that the distance (a) from the 4 plate hole to the side is greater than (b), and which side of (a) is in front.

M	x2
Ø5x40mm	

B	x2
Ø15x10mm	

X	x1
M4mm	

5




B	x2
Ø15x10mm	


M	x2
Ø5x40mm	

X	x1
M4mm	


6




7




8





9



10




11




B	x7
	
15x10mm	

12





C	x4
	
6x30mm	

13




14






I	x2
	


J	x4
	
Ø4x12mm	

Y	x1
	


16




17



18




Attention,
First hole




Attention,
First hole

E	x6	Y	x1
			
3x12mm			


19



20





21





U	x2	T	x1	Y	x1
					
3x14mm					

22




B	x1	C	x1
			
15x10mm		6x30mm	
M	x2	X	x1
			
5x40mm		M4mm	

23




B	x1	C	x1	M	x2	X	x1
							
15x10mm		6x30mm		5x40mm		M4mm	

24




C	x4	F	x4
			
6x30mm		20mm	


25




26




27





A






x2



A	x4
	
6x35mm	

Y	x1
	


28




B	x4
	
15x10mm	

C	x4
	
6x30mm	


29




30






31




32






B	x4
15x10mm	


34




35





36



37









Y	x1	K	x16	L	x16
					
				3x16mm	

40




Y	x1	D	x5
			
		4x35mm	

41





Y	x1	A	x5	B	x5
					
		6x35mm		15x10mm	

42



43








44




Peel off the back covering







Paste the accessory W-1 on the plate





The fitting w can be pasted on any plate according to the user's needs



Pull the folding rack hard to the sides





D	x2	S	x2	Y	x1
					
Ø4x35mm					