




1




THE CONNECTION TUBE IS PASSED THROUGH THE HOLES IN THE UPPER PART OF THE PRODUCT AND CONNECTED WITH THE CONNECTION SHEET BAR AS SHOWN.



x2



CONNECTION SHEET BAR





x4

CONNECTION TUBE OF THE TOP PART


2



THE HOLES LOCATED IN THE BOTTOM PART OF THE BASE ARE PASSED THROUGH THE CONNECTION TUBE MOUNTED ON THE TOP PART OF THE PRODUCT.




TOP PART OF THE PRODUCT




x4

CONNECTION TUBE OF THE TOP PART



x2

CONNECTION SHEET BAR



TOP PART OF THE PRODUCT