




Ax1 	Bx1 	C1x1 	Dx1 	Ex2 
Fx4 	Gx2 	C2x1  Hx6  $\frac{\Phi 6 \times 50}{\Phi 0.2 \times 2.0}$		
		Ix6  $\frac{\Phi 4 \times 30}{\Phi 0.2 \times 1.2}$		Jx1 

1




mm


inch

x2

2



3



4

