



List of standard parts

1




As shown in the diagram, wrap the threads with PTFE tape.

4




Attach the mounting rod to the brackets. Tighten the screws with a hex key to complete the installation

2



Screw the connector onto the pipe threads to complete this step

3



Drill holes according to the marked positions on the mounting rod, then insert wall anchors into the holes, and secure the two mounting brackets to the wall using self-tapping screws

