






nr	L[mm]	B[mm]	T[mm]	Menge	Colli
1	920	770	19	1	1/2





I







G46



6x8

x...(4)






II

W4






2x






III







IV




1




2






3








4






5








A = A





nr	L[mm]	B[mm]	T[mm]	Menge	Colli
1	920	770	19	1	1/2





I







G46



6x8

x...(4)






II

W4






2x






III







IV




1




2





3



4



5



A = A

