


Tools Recommended

EN_IMPORTANT, RETAIN FOR FUTURE REFERENCE: READ CAREFULLY.


FR_IMPORTANT: A LIRE ATTENTIVEMENT ET À CONSERVER POUR CONSULTATION ULTÉRIEURE.

ES_IMPORTANTE, LEA Y GUARDE PARA FUTURAS REFERENCIAS.


PT_IMPORTANTE, RETER PARA REFERÊNCIA FUTURA: LEIA ATENTAMENTE.

DE_WICHTIG! SORGFÄLTIG LESEN UND FÜR SPÄTER NACHSCHLAGEN AUFBEWAHREN.


IT_IMPORTANTE! CONSERVARE IL PRESENTE MANUALE PER FUTURO RIFERIMENTO E LEGGERLO ATTENTAMENTE.




①x02




⑧x04




②x01




⑨x02




③x01




⑩x01




④x02




⑪x01




⑤x02




⑫x01




⑥x01



⑬x01




⑦x01




⑭x02


15x04




16x03




17x02




18x01




19x01





A x01**F x06+1(spare)****B x12+1(spare)**



M3*10

G x04+1(spare)



M3.5*45

C x48+2(spare)**H x02**


M3.5*40

D x14+1(spare)**I x02**

M3*25







E x08+1(spare)**J x02**






M3*16




EN_ Do not confuse similar screws.
FR_ Ne pas confondre des vis similaires.
ES_ No confunda tornillos similares.
PT_ Não confundir parafusos semelhantes.
DE_ Verwechseln Sie ähnliche Schrauben nicht.
IT_ Non confondere le viti simili.


NOTE





Ax01**H**x02**I**x02**C**x04

M3.5*40





Dx04

M3*25



**F**x02

M3*10




Cx06



M3.5*40

**C**x04

M3.5*40




Dx04

M3*25










Fx02


M3*10

**C**x06





M3.5*40






Ex04


M3*16

Jx01**C**x07



M3.5*40

12


C

Cx08

M3.5*40

**D**x06

M3*25



Done