



PACKING LIST



Ax2 Bx2 Cx2 Dx1




Fx4 Gx1 Hx1



Jx1



Kx2



Lx2



x200



x7



x1



x1



M1x4
6x40mm



M2x2
6x50mm



M3x12
4x16mm