



ASSEMBLY INSTRUCTIONS



A




B

C

TURN TOP UPSIDE DOWN ON A SOFT WORKING SURFACE.

a		x8	b		x8	c		x1

STEP1



STEP2

