

ASSEMBLY INSTRUCTIONS

BED, 6/6 UPH




DEAR CUSTOMER,

Caution: Please read all instructions before assembly and check the carton for any parts that may have come loose during shipment. It is recommended to use two or more persons during the assembly process.


HARDWARE LIST:

No.	Description	Sketch	Size	Quantity
1	Full-thread bolt		Ø5/16" x 80mm	18 PCS
2	Curve washer		Ø5/16"	18 PCS
3	Hex nut		Ø5/16" x 18mm	18 PCS
4	Open Wrench		1/2" x 90 mm	1 PC
5	Screw		Ø4 x 30mm	8 PCS

PARTS LIST:

No.	Description	Sketch	Quantity
A	Headboard		1PC
B	H/B side panel (L & R)		2 PCS
C	Footboard		1 PC
D	Bed Side Rail		2PCS
E	Slat		4 PCS
F	Support Legs		8 PCS

Step 1:



Step 1: Attach Headboard (A) to H/B side panel (B) by using by using Full-thread bolt (1), Curve washer (2), Hex nut (3) and Open wrench (4).


ASSEMBLY INSTRUCTIONS

BED, 6/6 UPH

DEAR CUSTOMER,


Caution: Please read all instructions before assembly and check the carton for any parts that may have come loose during shipment. It is recommended to use two or more persons during the assembly process.

Step 2:




Step 2: Attach Bed side rail (D) to Footboard (C) and H/B side panel (B) by using Full-thread bolt (1), Curve washer (2), Hex nut (3) and Open wrench (4).

Step 3:



Step 3: Attach Support Legs (F) to Slat (E) .

Step 4:



Step 4: Attach Slat (E) to Bed side rail (D) by using Screw (5) and Screw driver (not include).