


ASSEMBLY INSTRUCTION




PARTS LIST




A

X1




B

X1



C


X1



D

X1

HARDWARE LIST




1

X2



2

X4



M8X60

3

X2



M5

4

X1






M5X50


5

X4



BOX-1




BOX-2




Step1






Step2




Step3





Step4



ASSEMBLY INSTRUCTION




PARTS LIST


		
A	B	C
X1	X1	X1

HARDWARE LIST



1
X4






Step1




Step2




Step3




ASSEMBLY INSTRUCTION




PARTS LIST




A X1




B X1



C X1



D X1



E X1


HARDWARE LIST




1 X4




X1




X1



A




X1



X1


1 X4

Step1




A




Step2




Step3






Step4




ASSEMBLY INSTRUCTION




PARTS LIST


			
A	B	C	D
x1	x1	x1	x2

HARDWARE LIST


									
1	X4	2	X4	3	M6X25	X8	4	M4	X1




Step1





Step2




Step3







Step4





ASSEMBLY INSTRUCTION




PARTS LIST


			
A	B	C	D
X1	X1	X1	X1

HARDWARE LIST


				
1	2	3	4	5
X2	X3	M8X60 X2	M5 X1	M5X50 X4




Step1




Step2





Step3




Step4




Step5








ASSEMBLY INSTRUCTION



PARTS LIST



HARDWARE LIST



Step4

