


Assembly instructions for the bed frame, including tool requirements, estimated time, and personnel needed.

Tools: A circle containing icons for an Allen key, a screwdriver, and a wrench. A power drill icon is crossed out with a diagonal line, indicating it is not required.


Time: A clock icon with the text "30'" below it, indicating an estimated assembly time of 30 minutes.

Personnel: A person icon with the number "2" below it, indicating that two people are required for assembly.

Warnings: Two warning triangles (exclamation marks) are present. The top one is connected to the tools section, and the bottom one is connected to the personnel section.




1




x 1

2




x 1

3




x 2

4




x 1

5




x 2

6



x 4

7




x 1

8




x 1

9




x 1

A




x 16

B




x 6

C




x 8

D




x 8

E




x 24

F




x 1

G




x 6

H



x 1

I




x 4

J






x 1

K






x 6




1






2



3




4




5

7




x 1

8



x 1

B




x 6

F






x 1

G




x 6



6

9



x 1

K



x 6

