


Ax4




Bx2



Cx2




Dx1




Ex2




Fx1




Gx4



CLx1




CRx1



DRx1



DLx1



Hx32



Ix36



Jx32



Kx30



Lx40



Mx4




Nx4



Ox4




Px4




①

CLx1



Lx3




CLx1

a

②

Lx3



CRx1

b

CRx1



Lx3





③

Ix12



Hx12






④

Jx12



Jx12



⑤


Nx2



Mx2




Lx16



©

⑥



Ix4

D

Hx4

E


Ix4



Hx4



⑦




Jx4



Jx4

8



Ox4



Px4




Ox1

Px1

x4

1.3
0.1

9




Kx30




Kx30

10



11




12

Ix12




Hx12



13

Jx12




14

lx8



Hx4




15

Jx4



Jx4



16

Nx2




Mx2



Lx16




Lx16
Mx2



f

17



18

