



ASSEMBLY INSTRUCTION
































IMPORTANT NOTE:
















- ① PLACE ALL PARTS ON A CLEAN AND SMOOTH SURFACE SUCH AS A RUG OR CARPET TO AVOID THE PARTS FROM BEING SCRATCHED.
- ② BEFORE YOU BEGIN, KINDLY FOLLOW THE ASSEMBLY INSTRUCTIONS STEP BY STEP.
- ③ DO NOT TIGHTEN ALL SCREWS AND BOLTS UNTIL THIS ITEM IS FULLY SET-UP.

Detail View



1		2		3		4	
	1pc		1pc		1pc		1pc
5		6		7		8	
	1pc		1pc		1pc		1pc
9		10		11		12	
	1pc		1pc		1pc		1pc
13		14		15		16	
	1pc		2pcs		4pcs		1pc
17		18		19		20	
	1pc		2pcs		2pcs		1pc
21		22		23		24	
	2pcs		2pcs		1pc		1pc
25		26		27		28	
	1pc		1pc		1pc		1pc
29							
	1pc						


Hardware List


<p>A</p>  <p>Ø 3.5*45 24pcs</p>	<p>B</p>  <p>Ø 3.5*40 52pcs</p>	<p>C</p>  <p>Ø 3.0*30 20pcs</p>	<p>D</p>  <p>Ø 3.5*25 16pcs</p>
<p>E</p>  <p>Ø 3.0*16 16pcs</p>	<p>F</p>  <p>Ø 3.5*30 10pcs</p>	<p>G</p>  <p>Ø 3.0*16 2pcs</p>	<p>H</p>  <p>27pcs</p>
<p>I</p>  <p>2pcs</p>	<p>J</p>  <p>12pcs</p>	<p>K</p>  <p>1pc</p>	<p>L</p>  <p>4pcs</p>
<p>M</p>  <p>3pcs</p>	<p>N</p>  <p>2pcs</p>	<p>O</p>  <p>1pc</p>	

ASSEMBLY TOOLS REQUIRED(NOT INCLUDED)




PLEASE BE CAREFUL DO NOT DAMAGE THE HOLE POSITION WHEN YOU USE POWERTOOLS !






Step 3

B*2	C*1	M*3




Step 4

A*8




Step 5

A*8	D*16	L*4





Step 6

B*6	E*2	I*2





X2

Step 7





B*24


Step 8




Step 9



Step 10






Step 11




C*5



Step 12



B*8




Step 13




A*2



F*6



N*2




Step 14





B*12





E*2





Step 15




Step 16





Step 17



Step 18



Step 19



Step 20

