

1

Fasten the screws to 50%

2




A Fasten the screws to 50%

3

100%

Fasten the screws to 100%

3

- 
AX1
- 
BX2
- 
CX2
- 
M6X16mm
DX4
- 
M6X50mm
EX6
- 
FX6
- 
GX6
- 
HX1