









Diagram illustrating assembly instructions and safety warnings:

- Top Section:** Shows an Allen key icon and a crossed-out power drill icon, indicating that a power drill should not be used. A warning triangle with an exclamation mark is positioned to the right. Below this is a clock icon and the text "20'", indicating a 20-minute assembly time.
- Bottom Section:** Shows a diagram of a block being placed on a surface and a diagram of a block being lifted, both with a diagonal line through them, indicating that the table should be placed on a soft surface and not lifted. A warning triangle with an exclamation mark is positioned to the right. Below this is a person icon and the number "2", indicating that two people are required for assembly.



E 



E 


1 x 4




E 



E 




A




x 4

B




x 4

C




x 4

D




x 1

E




x 4

F






x 8

G



x 1

1



2

