









Installation Instruction




HARDWARE LIST




PARTA LIST

A x 46  Ø6 x 34mm	B x 46  Ø15 x 10mm	C x 4  Ø6*30mm	D x 4 	E x 12  Ø5 x 48mm
F x 1  M3	G x 1 	H x 12  Ø4*30mm	I x 3 	J x 3 
K x 26  M3*12mm	L x 8 	M x 8  Ø3*16mm	N x 6 	O x 12  M4X15
P x 3 CL CR DL DR 300mm	Q x 3  40*12*1mm/M3X12	R x 1  19*55*58D/M3X14	S x 1  120*20*12mm/M3X14	T x 6  Ø21*1mm


Parts List




1X1PCS




2X1PCS




3X1PCS




4X1PCS




5X1PCS




6X1PCS




7X1PCS




8X1PCS




9X1PCS




10X1PCS




11X1PCS




12X1PCS




13X1PCS




14X1PCS




15X1PCS




16X1PCS




17X3PCS




18X3PCS




19X3PCS




20X3PCS




21X3PCS



22X1PCS




23X1PCS



24X1PCS



Step 1

Ax 10



Ø6 x 34mm

Gx 1





Step 2

Bx 3



Ø15 x 10mm

Gx 1





Step 3

Bx 2



Ø15 x 10mm

Gx 1





Step 4

B x 3



Ø15 x 10mm

Gx 1




Step 5

Ex 2




Ø5 x 48mm

Fx 1




M3




Step 6

Rx 1




Ax 2





Ø6 x 34mm

Gx 1



Sx 1




Step 7

Kx 4



M3X12

Gx 1




Px 2

CL

CR

300mm




Step 8

Kx 4



M3X12

Gx 1




Px 2

CL

CR

300mm



Step 9

Ex 4




Ø5 x 48mm

Fx 1



M3





Step 10

Bx 2




Ø15 x 10mm

Gx 1





Step 11

Ax 14



Ø6 x 34mm

Gx 1




Step 12

Kx 4



M3X12



Gx 1




Px 2



300mm



Step 13




Step 14

Bx 10



Ø15 x 10mm

Gx 1




Ex 3




Ø5 x 48mm

Fx 1



M3




Step 15

Bx 6



Ø15 x 10mm

Gx 1




Ex 3




Ø5 x 48mm

Fx 1



M3





Step 16

Kx 2




M3X12mm



Gx 1



Step 17




Step 18





Step 19

Ax 8



Ø6 x 34mm

Gx 1





Step 20

Bx 8




Ø15 x 10mm

Gx 1





Step 21

A x 12




Ø6 x 34mm


Gx 1



Step 22




Step 23




Step 24


Hx 12


M3*30mm
Ax 12


Ø15 x 10mm
Gx 1




Step 25


Nx 3

Ox 6



M4X15
Gx 1







Step 26


Kx 12

M3*12mm
Px 6
DL 
DR 
300mm
Gx 1





Step 27


Nx 3	Qx 3
	  40*12*1mm/M3X12
Ox 6	
	
M4X15	
G x 1	
	
Jx 3	
	
Ix 3	
	




Step 28



Step 29



Step 30



Step 31



Lx8



Mx8



Ø3*16mm



Step 32

Tx 6



Ø21*1mm

