










CARE AND MAINTENANCE

Spot clean using a mild water-free solvent. Only a professional cleaner should undertake a complete overall cleaning.  
The use of steam or water-based cleaners may cause excessive shrinking or staining.


NOTICE

- \* Please make sure that you have all parts indicated before you begin assembly of this item
- \* This item should be assembled on a soft surface to prevent scratching the finish during assembly
- \* This item may require periodic tightening

Part List and Hardware List

PIECE	DESCRIPTION	PICTURE	QUANTITY
1	Top		1X
2	Leg-1		1X
3	Leg-2		1X
4	Connect 1		1X
5	Connect 2		1X
A	Allen bolt(M6x35 mm)		4X
B	Flat washer		10X
C	Allen bolt(M6x16 mm)		4X
D	Allen key		1X

Product Dimensions:55.1"x31.5"x28.3"H



ATTACH YOUR RECEIPT HERE

Serial Number \_\_\_\_\_

Purchase Date \_\_\_\_\_

PREPARATION

Before beginning assembly of product, make sure all parts are present. Compare parts with package contents list and hardware contents list.  
If any part is missing or damaged, do not attempt to assemble the product.  
Estimated Assembly Time: 30 minutes.  
Tools Required for Assembly (included): Allen Key

1

Diagram 1 shows the assembly of the top rail (5) to the side rail (2). Hardware A (screws) and hardware B (washers) are used to secure the connection. Hardware A is shown being inserted into the side rail, and hardware B is shown being placed over the screw head.

A

x2

M6 x 35mm

B

x2

2

Diagram 2 shows the assembly of the bottom rail (3) to the side rail (2). Hardware A (screws) and hardware B (washers) are used to secure the connection. Hardware A is shown being inserted into the side rail, and hardware B is shown being placed over the screw head.

A


x2

M6 x 35mm

B

x4

3



C x4



M6 x 16mm

B x4



4

