


















Assembly Instruction




A	X22	B	X22	C	X8	D	X6	E	X1	F	X4	G	X6	H	X2	I	X1
																	
M6x35mm		Ø15x9mm		M3.5x12mm		M3x16mm		4mm		M5x40mm		Ø8x30mm		M4x10mm			
J	X4	K	X6	M	X1	N	X4	O	X2	P	X2	Q	X2	R	X2		
																	
		M4x35mm				M5x50mm				Ø6x30mm				M4x12mm			




① 	② 	③ 	④ 
1PC	1PC	1PC	1PC
⑤ 	⑥ 	⑦ 	⑧ 
1PC	1PC	1PC	1PC
⑨ 	⑩ 	⑪ 	⑫ 
1PC	1PC	1PC	1PC
⑬ 	⑭ 	⑮ 	
1PC	1PC	1PC	

1



A	X4
	
M6x35mm	


2




O	X1
	

C	X3
	
M3.5x12mm	


3



4




5




Q	X2	R	X2	A	X4
					
		M4x12mm		M6x35mm	

6




B	X4	G	X2
			
Ø15x9mm		Ø8x30mm	

7




8



A	X6
	
M6x35mm	


9



G	X2
	
Ø8x30mm	

N	X4
	
M5x50mm	

10




A	X4
	
M6x35mm	


B	X4
	
Ø15x9mm	

F	X4
	
M5x40mm	


11



12




13



M	X1
	

D	X2
	
M3x16mm	


14



K	X2
	
M4x35mm	


P	X2
	
Ø6x30mm	

15




K	X4
	
M4x35mm	


16





17



18





H	X2
	
M4x10mm	