



DIAGRAM A



SEE  
DIAGRAM  
B

DIAGRAM B



Connect all wiring into centre power cord.  
Cap wiring.

Step 8 and Step 9

- Step 1. (not shown) Shut off power source at breaker box.
- Step 2. Connect wires and hang using canopy.
- Step 3. Insert seven arms into center stem. Attach using lock washer and nut.
- Step 4. Hang rings and prisms over arms seven times.
- Step 5. Place bobeche over arm.
- Step 6. Place glass cup over arm and onto bobeche.
- Step 7. Slip candelabra cover over arm. (insert light bulb)
- Step 8. Connect all wiring into center power cord. (test at this point before closing)
- Step 9. Cap wiring using glass bobeche.
- Step 10. Place prisms on all bobeche as shown.
- Step 11. Place glass ball on bottom.
- Step 12. Take glass beaded chain with prism and open as shown. Hook top of chain on top bobeche and two side chains onto each bobeche as shown. Repeat seven times between each set of lights.